

VEHICLE DETAILS

2005 SUBARU OUTBACK LL BEAN - 4Dr CUV - 4S4BP86C854359564 - Lane Number 19 - Run Number 766

EXT COLOR/Code: CHAMPGNE INT COLOR/Code: BEI Mileage: 35,893
Work Order #: 5520701 Rcv Date: 11/08/2007
Seller: POHANKA CHEVROLET INC Inspector: JWIEHOLD 11/13/2007

VEHICLE IMAGES/OPTIONS



Overall Image
Not Available

OPTIONS

- Pwr Lock
- Pwr Window
- Tilt Steering
- Cruise Ctl
- AM/FM Radio
- Dual Air Bags
- Power Mirrors
- Fog Lamps
- Rear Wiper
- Power Trunk/Liftgate
- Luggage Rack
- Satellite Radio - XM /
- Pwr Steering
- Pwr Seats - Both
- A/C
- Rear Defrost
- Side Air Bags
- ABS Brakes
- Owner's Manual
- CD Changer - OEM - 6.00
- Heated Seats
- Dual Air Conditioning

AFTERMARKET

- Trip Counter
- Rear Tail/Lift Gate
- Steering Wheel Audio Control
- Pwr Glass Sun Roof

- 5 Passenger Seating
- Security System
- Trip Computer
- Woodgrain Interior Package
- Turn Signal Mirrors

VEHICLE INFORMATION

MECHANICAL

- 6 Cylinder Gas
- Automatic
- AWD
- Pwr Brakes
- 3.0 L

TIRES AND WHEELS

Tire	Tread Depth	Brand	Size
Left Front:	9/32"	BRIDGESTONE	225/55R17
Right Front:	9/32"	BRIDGESTONE	225/55R17
Left Rear:	9/32"	BRIDGESTONE	225/55R17
Right Rear:	9/32"	BRIDGESTONE	225/55R17
Spare:	0/32"	Mini	

Tire Condition: Good

Wheels: Alloy

INTERIOR

- Clean
- BEI - Leather
- Int Odor: OK
- Regular Dash

KEYS

- Combo Key - 1

GRADING



- Certified - No
- [Grade 3, Average](#)
- Drivable - Yes

ADDITIONAL INFORMATION

T/A

DAMAGES - SUGGESTED REPAIRS

Suggested repairs are based on Manheim professional inspector's recommendation.
Total labor hours include paint, body or repair estimates.

	DESCRIPTION	CONDITION	SEVERITY	SUGGESTED REPAIR	TOTAL LABOR HOURS
 Overall Image Not Available	Front Bumper	Scratch Heavy	3" to 4"	Repair	4.00
	Hood	Multiple Chips	Less 1"	Touch Up	.00
 Overall Image Not Available	LR Door	Dent	9" to 10"	Repair	5.80
	L Qtr Panel	Ding	PDR/1	PDR	.00
	RF Door	Ding	PDR/1	PDR	.00
	RR Door	Dings	PDR/3	PDR	.00
	R Qtr Panel	Dings	PDR/2	PDR	.00
	Windshield	Multiple Chips	Less 1"		.00
	Rear Bumper	Prev Repair	Acceptable	No Action Required	.00
TOTALS					9.80