

2005 CADILLAC ESCALADE AWD - WHITE

VIN: 1GYEK63N25R163479 Work Order #: 2703623 **MANHEIM AUTO AUCTION**

1GYEK63N25R163479 **Body Style:** 4Dr SUV - Sun Roof

Ext Color/Code: WHITE Int Color/Code: BEI Mileage: 37.120

Seller: ADCOCK BROTHERS

Title State: PΑ Certified: No

Condition/Grade: Grade 4, Clean

Sale: 72 Lane: 7 137 Run:

Inspection: IVANG 11/27/2007

Drivable: Yes





Overall Image Not Available

VEHICLE INFORMATION

MECHANICAL

8 Cylinder Gas Automatic **AWD** Pwr Brakes 6.0 L

INTERIOR

Clean BEI - Leather

Odometer - 6 Digits Digital -

Operable Int Odor: OK Wood Trim Dash

KEYS

Master Key - 1

OPTIONS

Pwr Lock Pwr Window Tilt Steering Cruise Ctl CD Plaver Dual Air Bags

Power Mirrors Power Folding Mirrors **ABS Brakes**

4 Door Trip Counter CD Changer - OEM -

6.00

Warranty Books Third Seat

On-Board Computer Satellite Radio - XM 7 Passenger Seating US EPA Label

Step Bumper

Steering Wheel Audio

Control Traction Control HomeLink

Heated Seats Memory Seat Woodgrain Interior

Package

Turn Signal Mirrors Parking Distance

Control Headphones Pwr Steering Pwr Seats - Both

A/C

Rear Defrost Side Air Bags 50 State Emissions **Heated Mirrors** Owner's Manual Premium Stereo -

BOSE Fog Lamps Rear Air Conditioning Rear Wiper Trip Computer Luggage Rack Floor Mats Spoiler

Xenon Headlights Security System Running Board Trailer Hitch **Dual Air** Conditioning On-Star

Heated Rear Seats DVD with Screen Adjustable Pedals Navigation System Rear Radio Controls

FLUID LEVELS

Fuel Level: 1/4

TIRES AND WHEELS

Left 7/32" GOODYEAR 265/70R17 Remote Key/Fob - 1 Front:

Right 9/32" GOODYEAR 265/70R17 Front: Left Rear: 7/32" GOODYEAR 265/70R17 Right 7/32" GOODYEAR 265/70R17 Rear: Spare: 12/32" GOODYEAR 265/70R17

Tire Condition: Average Wheels: Chrome

ANNOUNCED CONDITION:

INTERNET REMARKS:

REMARKS/ADDITIONAL DAMAGE:

DISCLOSURES:

NOTES TO CONSIGNOR: *MAA BRONZE SELLER

REMARKS: *MAA BRONZE SELLER

2005 CADILLAC ESCALADE AWD - WHITE

VIN: 1GYEK63N25R163479 Work Order #: 2703623
MANHEIM AUTO AUCTION

DAMAGES

	DESCRIPTION	CONDITION	SEVERITY	REPAIR HOURS	PAINT HOURS	PART HOURS	HOURS
Overall Image Not Available	Overall Picture	Ovrall Picture		.00	.00	.00	.00
Overall Image Not Available	Overall Picture	Ovrall Picture		.00	.00	.00	.00
Overall Image Not Available	Overall Picture	Ovrall Picture		.00	.00	.00	.00
Overall Image Not Available	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	LF Door	Ding	PDR/1	.00	.00	.00	.00
	Rear Bumper	Gouged	2" to 3"	.00	.00	.00	.00
			TOTALS	.00	.00	.00	.00

Print