



2004 SUBARU FORESTER AWD XS - BLACK

VIN: JF1SG65684H743359 Work Order #: 4494136

MANHEIM AUTO AUCTION

VIN: JF1SG65684H743359
Body Style: 4Dr CUV - Sun Roof
Ext Color/Code: BLACK
Int Color/Code: GRY
Mileage: 13,287
Seller: CHASE VEHICLE EXCHANGE
Certified: No
Condition/Grade: Grade 3, Average
Sale: 63
Lane: 19
Run: 519
Inspection: RDAVIS 10/12/2007
Drivable: Yes



VEHICLE INFORMATION

MECHANICAL

4 Cylinder Gas
 Automatic
 AWD
 Pwr Brakes

FLUID LEVELS

Fuel Level: 1/2

TIRES AND WHEELS

Left Front: 6/32" YOKOHAMA 215/60R16
 Right Front: 6/32" YOKOHAMA 215/60R16
 Left Rear: 6/32" YOKOHAMA 215/60R16
 Right Rear: 5/32" YOKOHAMA 215/60R16
 Spare: 10/32" YOKOHAMA 215/60R16

Tire Condition:

Wheels: Alloy

ANNOUNCED CONDITION:

INTERNET REMARKS:

REMARKS/ADDITIONAL DAMAGE:

DISCLOSURES:

NOTES TO CONSIGNOR:

REMARKS:

INTERIOR

Average
 GRY - Leather
 Int Odor: OK
 Regular Dash

KEYS

Master Key - 2
 Remote Key/Fob - 2

OPTIONS

Pwr Lock
 Pwr Window
 A/C
 Rear Defrost
 Side Air Bags
 50 State Emissions
 Owner's Manual
 CD Changer - OEM - 6.00
 Heated Seats
 Luggage Rack
 5 Passenger Seating
 Security System
 Rear Tail/Lift Gate
 Cargo Cover







Pwr Steering
 Tilt Steering
 Cruise Ctl
 CD Player
 Dual Air Bags
 Power Mirrors
 4 Door
 Rear Wiper
 NO Rear Air Conditioning
 NO Third Seat
 US EPA Label
 Trip Counter
 Floor Mats
 ABS Brakes

2004 SUBARU FORESTER AWD XS - BLACK

VIN: JF1SG65684H743359 Work Order #: 4494136

MANHEIM AUTO AUCTION

DAMAGES

	DESCRIPTION	CONDITION	SEVERITY	REPAIR HOURS	PAINT HOURS	PART HOURS	TOTAL HOURS
	Front Bumper	Dent	1" to 2"	1.00	2.50	.00	3.50
	RF Door	Multiple Dents	2" to 3"	2.00	2.80	.00	4.80
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Front Bumper	Prev Repair	Substd Repair	.00	.00	.00	.00
	Hood	Chipped	Less 1"	.00	.00	.00	.00
	LF Door	Ding	PDR/1	.00	.00	.00	.00
	LF Door Molding	Chipped	1" to 2"	.00	.00	.00	.00
	LF Door Edge	Chipped	Less 1"	.00	.00	.00	.00
	LR Door	Dings	PDR/2	.00	.00	.00	.00
	L Qtr Panel	Ding	Less 1"	.00	.00	.00	.00
	Rear Body Panel	Bent	Less 1"	.00	.00	.00	.00
	Lift Gate	Scratch Light	1" to 2"	.00	.00	.00	.00
	Rear Bumper	Prev Repair	Substd Repair	.00	.00	.00	.00
	R Bumper Step P	Gouged	Less 1"	.00	.00	.00	.00
	RF Fender	Ding	PDR/1	.00	.00	.00	.00
	RR Door	Dings	PDR/3	.00	.00	.00	.00
	RR Wheel	Scratches	Less 1"	.00	.00	.00	.00
			TOTALS	3.00	5.30	.00	8.30

Print