



# 2004 SUBARU OUTBACK LL BEAN - LT GREEN

VIN: 4S3BH806947618919 Work Order #: 4494109

MANHEIM AUTO AUCTION

**VIN:** 4S3BH806947618919  
**Body Style:** 4Dr CUV - Sun Roof  
**Ext Color/Code:** LT GREEN  
**Int Color/Code:** BEI  
**Mileage:** 60,364  
**Seller:** CHASE VEHICLE EXCHANGE  
  
**Title State:** NY  
**Certified:** No  
**Condition/Grade:** Grade 3, Average  
**Sale:** 67  
**Lane:** 19  
**Run:** 537  
**Inspection:** JGRABY 11/01/2007  
**Drivable:** Yes



## VEHICLE INFORMATION

### MECHANICAL

6 Cylinder Gas  
 Automatic  
 AWD  
 Pwr Brakes  
 3.0 L

### INTERIOR

Average  
 BEI - Leather  
 Odometer - 6 Digits Digital - Operable  
 Int Odor: OK  
 Regular Dash

### OPTIONS

|               |                          |
|---------------|--------------------------|
| Pwr Lock      | Pwr Steering             |
| Pwr Window    | Pwr Seats - Drivers Only |
| Tilt Steering | A/C                      |
| Cruise Ctl    | Rear Defrost             |
| CD Player     | Side Air Bags            |
| Dual Air Bags | ABS Brakes               |
| Power         | Heated Mirrors           |
| Mirrors       | Heated Seats             |
| Rear Wiper    | On-Star                  |
| Luggage       | Security System          |
| Rack          | Woodgrain Interior       |
| US EPA        | Package                  |
| Label         |                          |
| Trip Counter  |                          |

### FLUID LEVELS

Fuel Level: 1/8

### TIRES AND WHEELS

Left Front: 9/32" GENERIC 225/60R16  
 Right Front: 9/32" GENERIC 225/60R16  
 Left Rear: 10/32" GENERIC 225/60R16  
 Right Rear: 10/32" GENERIC 225/60R16  
 Spare: 10/32" 225/60R16

### KEYS

Master Key - 2  
 Remote Key/Fob - 2

**Tire Condition:** Average

**Wheels:** Alloy

**ANNOUNCED CONDITION:**

**INTERNET REMARKS:**

**REMARKS/ADDITIONAL DAMAGE:**

**DISCLOSURES:**

**NOTES TO CONSIGNOR:**





**REMARKS:**

## 2004 SUBARU OUTBACK LL BEAN - LT GREEN

VIN: 4S3BH806947618919    Work Order #: 4494109

MANHEIM AUTO AUCTION

### DAMAGES

|  | DESCRIPTION     | CONDITION      | SEVERITY      | REPAIR HOURS | PAINT HOURS | PART HOURS | TOTAL HOURS |
|--|-----------------|----------------|---------------|--------------|-------------|------------|-------------|
|  | Front Bumper    | Dent/Paint Dmg | 2" to 3"      | .00          | .00         | .00        | .00         |
|  | LR Door         | Chipped        | Less 1"       | .00          | .00         | .00        | .00         |
|  | LR Door         | Dings          | PDR/4         | .00          | .00         | .00        | .00         |
|  | L Qtr Panel     | Dings          | PDR/4         | .00          | .00         | .00        | .00         |
|  | Rear Bumper     | Gouged         | 1" to 2"      | .00          | .00         | .00        | .00         |
|  | Overall Picture | Ovrall Picture |               | .00          | .00         | .00        | .00         |
|  | Overall Picture | Ovrall Picture |               | .00          | .00         | .00        | .00         |
|  | Overall Picture | Ovrall Picture |               | .00          | .00         | .00        | .00         |
|  | Overall Picture | Ovrall Picture |               | .00          | .00         | .00        | .00         |
|  | Hood            | Dings          | PDR/3         | .00          | .00         | .00        | .00         |
|  | LF Door         | Chipped        | Less 1"       | .00          | .00         | .00        | .00         |
|  | Rear Bumper     | Prev Repair    |               | .00          | .00         | .00        | .00         |
|  | RF Fender       | Scratch Light  | 1" to 2"      | .00          | .00         | .00        | .00         |
|  | RF Door         | Dings          | PDR/1         | .00          | .00         | .00        | .00         |
|  | RR Door         | Dings          | PDR/3         | .00          | .00         | .00        | .00         |
|  | R Qtr Panel     | Dings          | PDR/2         | .00          | .00         | .00        | .00         |
|  | R Qtr Panel     | Prev Repair    |               | .00          | .00         | .00        | .00         |
|  |                 |                | <b>TOTALS</b> | .00          | .00         | .00        | .00         |

### REPAIRED

|  | DESCRIPTION | CONDITION | SEVERITY      | REPAIR HOURS | PAINT HOURS | PART HOURS | TOTAL HOURS |
|--|-------------|-----------|---------------|--------------|-------------|------------|-------------|
|  | LR Door     | Ding      |               | .00          | .00         | .00        | .00         |
|  |             |           | <b>TOTALS</b> | .00          | .00         | .00        | .00         |

Print