



2004 LEXUS RX330 - BLACK

VIN: 2T2HA31U24C032331 Work Order #: 7417699

MANHEIM AUTO AUCTION

VIN: 2T2HA31U24C032331
Body Style: 4Dr SUV - Sun Roof
Ext Color/Code: BLACK
Int Color/Code: GRY
Mileage: 22,604
Seller: R M HOLLENSHEAD
 AUTO SALES INC
Title State: PA
Certified: No
Condition/Grade: Grade 4, Clean
Sale: 7
Lane: 22
Run: 39
Inspection: RDAVIS 01/31/2008
Drivable: Yes



VEHICLE INFORMATION

MECHANICAL

6 Cylinder Gas
 Automatic
 4X4
 Pwr Brakes
 3.3 L

FLUID LEVELS

Fuel Level: Unknown

TIRES AND WHEELS

Tire	Tread Depth	Brand	Size
Left Front:	6/32"	MICHELIN	235/55R18
Right Front:	7/32"	MICHELIN	235/55R18
Left Rear:	6/32"	MICHELIN	235/55R18
Right Rear:	7/32"	MICHELIN	235/55R18
Spare:	0/32"	NA	

Tire Condition: Average
Wheels: Alloy

INTERIOR OPTIONS

Clean	Pwr Lock	Pwr Steering
GRY - Leather	Pwr Window	Pwr Seats - Both
Int Odor: OK	A/C	Cruise Ctl
Regular Dash	Rear Defrost	Tape/CD
	Side Air Bags	Dual Air Bags
	Power Mirrors	Heated Mirrors
	ABS Brakes	Tinted Windows
	4 Door	Fog Lamps
	Trip Counter	CD Changer - OEM - 6.00
	Rear Wiper	NO Rear Air Conditioning
	Power Trunk/Liftgate	Trip Computer
	Luggage Rack	NO Third Seat
	5 Passenger Seating	Xenon Headlights
	Security System	Steering Wheel Audio Control
	Traction Control	Dual Air Conditioning
	HomeLink	Heated Seats
	Wheel Locks	Memory Seat
	Rear View Camera	Woodgrain Interior Package
	Power Telescopic Steering	Power Tilt Steering
	Navigation System	Rain Sensor Windshield Control
	Directional Stability Control	

KEYS

ANNOUNCED CONDITION: T/A

INTERNET REMARKS:

REMARKS/ADDITIONAL DAMAGE:

DISCLOSURES:

NOTES TO CONSIGNOR: ***MANHEIM'S #1 SELLER***





REMARKS: ***MANHEIM'S #1 SELLER***

2004 LEXUS RX330 - BLACK

VIN: 2T2HA31U24C032331 Work Order #: 7417699

MANHEIM AUTO AUCTION

DAMAGES

	DESCRIPTION	CONDITION	SEVERITY	REPAIR HOURS	PAINT HOURS	PART HOURS	TOTAL HOURS
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Front Bumper	Chipped	Less 1"	.00	.00	.00	.00
	Hood	Chipped	Less 1"	.00	.00	.00	.00
	LF Wheel	Scratches	Less 1"	.00	.00	.00	.00
	Rear Bumper	Poor Repair DULL PNT	GR 12"	.00	.00	.00	.00
	Spare Tire	Missing	None	.00	.00	.00	.00
			TOTALS	.00	.00	.00	.00

Print