

2005 LEXUS LS430 - BLACK

VIN: JTHBN36F155007457 Work Order #: 6721769 **MANHEIM AUTO AUCTION**

VIN: Body Style: Ext Color/Code: Int Color/Code: Mileage:	JTHBN36F155007457 4DSN - Sun Roof BLACK - 202 BEI - LA08 26,985					
ECM Mileage:						
Seller:	LEXUS FINANCIAL SERVICES/EASTERN					
Title State:	MA					
Certified:	No					
Condition/Grade: 4.0, Clean						
Sale:	42					
Lane:	20					
Run:	509					
Inspection:	CTUGEND 06/20/2008					
Drivable:	Yes					
Factory Category:	L					







INTERIOR OPTIONS Clean BEI - Leather Int Odor: OK Wood Trim Dash

KEYS

Master Key - 2

Valet Key - 1

Pwr Lock Pwr Window A/C Rear Defrost Side Air Bags Power Mirrors Power Folding Mirrors **ABS Brakes** 4 Door Trip Counter NO Rear Air Conditioning Warranty Books NO Third Seat Two-Wheel Drive Floor Mats US EPA Label Steering Wheel Audio Control Dual Air Conditioning Heated Seats Wheel Locks Memory Seat Woodgrain Interior Package Power Tilt Steering Rain Sensor Windshield Parking Distance Control Hand Tool Kit

Pwr Steering Pwr Seats - Both Cruise Ctl Tape/CD Dual Air Bags Heated Mirrors Owner's Manual Premium Stereo - MARK **LEVINSON** Fog Lamps CD Changer - OEM - 6.00 Power Trunk/Liftgate Trip Computer Keyless Entry 5 Passenger Seating Xenon Headlights Security System Traction Control HomeLink Heated Rear Seats Cooled Seats Rear View Camera Power Telescopic Steering Navigation System Directional Stability Control Sunshade - Power First Aid Kit

VEHICLE INFORMATION

MECHANICAL

8 Cylinder Gas
Automatic
4X2
Pwr Brakes
4.3 L

FLUID LEVELS

Fuel Level: Empty

TIRES AND WHEELS

Tire 6/32"

- Left Front: Left Rear: Right Front: Right Rear:
- Spare: Tire Condition: Average Wheels: Alloy

Tread Depth Brand Size DUNLOP 245/45R18 DUNLOP 245/45R18 DUNLOP 245/45R18 DUNLOP 245/45R18 DUNLOP

7/32"

5/32"

6/32"

10/32"

ANNOUNCED CONDITION: NAV,2 MASTERS KEYS,1 KNOB, Nav **INTERNET REMARKS: REMARKS/ADDITIONAL DAMAGE: DISCLOSURES: BAGGED 2MASTERS,1KNOB NO WARNING LIGHTS ARE ON** NOTES TO CONSIGNOR: **REMARKS:**

2005 LEXUS LS430 - BLACK

VIN: JTHBN36F155007457 Work Order #: 6721769 MANHEIM AUTO AUCTION

	DESCRIPTION	CONDITION	SEVERITY	REPAIR HOURS	PAINT HOURS	PART HOURS	TOTAL HOURS
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
MPH 16	Overall Picture	Ovrall Picture		.00	.00	.00	.00
4 8	Sun Roof	Factory	None	.00	.00	.00	.00
	Rear Lamps	Faded CONDENSATION IN LAMPS	None	.00	.00	.00	.00
	Rear Bumper	Prev Repair & LT SCRATCHES	Acceptable	.00	.00	.00	.00
	RF Door	Scratch Light	4" to 5"	.00	.00	.00	.00
	RR Wheel	Scratches ON LIP	4" to 5"	.00	.00	.00	.00
Sameda	Navigation Syst	Factory	None	.00	.00	.00	.00
	Nav Disc	Factory INACCESSIBLE	None	.00	.00	.00	.00
			TOTALS	.00	.00	.00	.00

Print