

VEHICLE DETAILS

2005 SUBARU OUTBACK XT LIMITED
VIN: 4S4BP67C654328414 **Body Style:** 4CUV **Top Type:** SR
EXT COLOR/Code: BLACK **INT COLOR/Code:** TAN **Mileage:** 38,982
Work Order #: 4496107 **Lane Number:** 19 **Run Number:** 528
Seller: CHASE VEHICLE EXCHANGE **Inspector:** DBOLTZ 07/18/2008 **Rcv Date:** 07/17/2008

VEHICLE IMAGES



GRADING



- **Certified** - No
- **Drivable** - Yes

VEHICLE INFORMATION

OPTIONS

- Pwr Lock
- Tilt Steering
- C
- Heated Mirrors
- Trip Counter
- Floor Mats
- Pwr Steering
- A/C
- Side Air Bags
- Owner's Manual
- CD Changer - OEM - 6.00
- Security System
- Pwr Window
- Cruise Ctl
- D Air Bags
- ABS Brakes
- Rear Wiper
- Dual Air Conditioning
- X
- Rear Defrost
- Power Mirrors
- Fog Lamps
- Luggage Rack
- Heated Seats

MECHANICAL

- 4GT
- A
- A
- X
- 2.5 L

INTERIOR

- Odometer - 6 Digits Digital - Operable
- TAN - L
- Int Odor: OK
- Wood Trim Dash

TIRES AND WHEELS

Tire Condition: Good **Wheels:** Alloy

KEYS

- Master Key - 1
- Remote Key/Fob - 1

Tire	Tread Depth	Brand	Size
Left Front:	8/32"	PIRELLI	235/55ZR17
Left Rear:	8/32"	PIRELLI	235/55ZR17
Right Front:	8/32"	PIRELLI	235/55ZR17
Right Rear:	8/32"	PIRELLI	235/55ZR17
Spare:	5/32"	BRIDGESTONE	235/55ZR17

ADDITIONAL INFORMATION

DAMAGES - SUGGESTED REPAIRS

Suggested repairs are based on Manheim professional inspector's recommendation.
Total labor hours include paint, body or repair estimates.

DESCRIPTION	CONDITION	SEVERITY	SUGGESTED REPAIR	TOTAL LABOR HOURS
Rear Bumper Cov	Scratch Light	Acceptable	No Action Required	.00
TOTALS				.00

VIN: 4S4BP67C654328414, Work Order #: 4496107