

**VEHICLE DETAILS**

**2005 SUBARU OUTBACK LIMITED**  
**VIN:** 4S4BP62C357377804      **Body Style:** 4CUV      **Top Type:** SR  
**EXT COLOR/Code:** LT GREEN- 39J      **INT COLOR/Code:** TAN- D80      **Mileage:** 40,152  
**Work Order #:** 4496545      **Lane Number:** 19      **Run Number:** 530  
**Seller:** CHASE VEHICLE EXCHANGE      **Inspector:** DBOLTZ 08/11/2008      **Rcv Date:** 08/08/2008

**VEHICLE IMAGES**



**GRADING**



Grade 4.9 Clean

- **Certified** - No
- **Drivable** - Yes

**VEHICLE INFORMATION**

**OPTIONS**

- Pwr Lock
- Tilt Steering
- C
- Heated Mirrors
- Trip Counter
- Floor Mats
- Heated Seats
- Pwr Steering
- A/C
- Side Air Bags
- Owner's Manual
- CD Changer - OEM - 6.00
- Security System
- Pwr Window
- Cruise Ctl
- D Air Bags
- ABS Brakes
- Rear Wiper
- Dual Air Conditioning
- D
- Rear Defrost
- Power Mirrors
- Fog Lamps
- Luggage Rack
- HomeLink

**MECHANICAL**

- 4G
- A
- A
- X
- 2.5 L

**INTERIOR**

- Odometer - 6 Digits Digital - Operable
- TAN - L
- Int Odor: OK
- Other Dash

**TIRES AND WHEELS**

**Tire Condition:** Poor      **Wheels:** Alloy

Tire	Tread Depth	Brand	Size
Left Front:	6/32"	BRIDGESTONE	225/60R16
Left Rear:	4/32"	BRIDGESTONE	225/60R16
Right Front:	5/32"	BRIDGESTONE	225/60R16
Right Rear:	4/32"	BRIDGESTONE	225/60R16
Spare:	5/32"	BRIDGESTONE	225/60R16

**KEYS**

- Master Key - 2
- Remote Key/Fob - 2
- Valet Key - 1

**ADDITIONAL INFORMATION**

**DAMAGES - SUGGESTED REPAIRS**

Suggested repairs are based on Manheim professional inspector's recommendation.  
Total labor hours include paint, body or repair estimates.

<b>DESCRIPTION</b>	<b>CONDITION</b>	<b>SEVERITY</b>	<b>SUGGESTED REPAIR</b>	<b>TOTAL LABOR HOURS</b>
Front Bumper Co	Mult Scratches	Less 1"	Airbrush	.00
LR Tire	Worn	None	Replace	.30
RR Tire	Worn	None	Replace	.30
			<b>TOTALS</b>	<b>.60</b>

**VIN: 4S4BP62C357377804, Work Order #: 4496545**