



MANHEIM AUTO AUCTION 1190 LANCASTER ROAD MANHEIM, PA 17545 (717) 665 - 3571

VEHICLE DETAILS

2006 SUBARU B9 TRIBECA

4S4WX85C364404270 4SUV VIN: **Body Style:** Top Type: SR EXT COLOR/Code: SLVR-58E INT COLOR/Code: GRY-F70 Mileage: 24,997 Work Order #: 4496577 Lane Number: 19 Run Number: 513 CHASE VEHICLE EXCHANGE Inspector: RSCHAEFFER 08/11/2008 Rcv Date: 08/07/2008 Seller:

VEHICLE IMAGES



GRADING



Grade 4.5 Clean

- Certified No
- Drivable Yes

VEHICLE INFORMATION

OPTIONS

- Pwr Lock
- Tilt Steering
- Heated Mirrors
- 4 Door
- Rear Air Conditioning
- Trip Computer
- Floor Mats
- Step Bumper
- HomeLink

- Pwr Steering
- A/C Side Air Bags
- Owner's Manual
- Fog Lamps
- CD Changer OEM 6.00
- Luggage RackUS EPA Label
- Steering Wheel Audio Control
- Rear Tail/Lift Gate

- Pwr Window
- Cruise Ctl
- D Air Bags
- ABS Brakes
- Maintenance Records
- Rear Wiper
- NO Third Seat
- Security System
- Traction Control
- Heated Seats

- Rear Defrost
- Power Mirrors
- Tinted Windows
- Trip Counter
- Warranty Books
- 5 Passenger Seating MP3 Compatible Stereo
- Dual Air Conditioning
- Turn Signal Mirrors

MECHANICAL

- 6G
- A
- A X
- 3.0 L

TIRES AND WHEELS

Tire Condition:	Good	Wheels:	Alloy	
Tire	Tread Depth	Brand	Size	
Left Front:	9/32"	KELLY	255/55R18	
Left Rear:	8/32"	KELLY	255/55R18	
Right Front:	9/32"	KELLY	255/55R18	
Right Rear:	9/32"	KELLY	255/55R18	
Spare:	4/32"			

INTERIOR

- Odometer 6 Digits Digital Operable
- Average
- GRY L
- Int Odor: OK
- Regular Dash

KEYS

- Master Key 2
- Remote Key/Fob 2

ADDITIONAL INFORMATION

DAMAGES - SUGGESTED REPAIRS

Suggested repairs are based on Manheim professional inspector's recommendation. Total labor hours include paint, body or repair estimates.

DESCRIPTION	CONDITION	SEVERITY	SUGGESTED REPAIR		LABOR HOURS
Front Bumper	Scratch Light	2" to 3"	Wet Sand		.50
Hood	Chipped	Less 1"	Touch Up		.00
Roof	Dings	PDR/7	PDR		.00
LR Door	Dings	PDR/2	PDR		.00
Spare Tire	Worn	None	Replace		.30
RR Door	Dings	PDR/2	PDR		.00
R Qtr Panel	Dings	PDR/2	PDR		.00
				TOTALS	.80

VIN: 4S4WX85C364404270, Work Order #: 4496577