

2004 VOLVO XC90 - BLACK

VIN: YV1CZ91H241094954 Work Order #: 2448905 **MANHEIM AUTO AUCTION**

YV1CZ91H241094954 **Body Style:** 4Dr CUV - Sun Roof

Ext Color/Code: BLACK Int Color/Code: BLK 50.723 Mileage:

Seller: HANN FINANCIAL

SERVICES

Title State: NY Certified: No

Condition/Grade: Grade 3, Average

Sale: 43 Lane: 20 697 Run: Inspection: **BBENTON**

07/03/2007

Drivable: Yes









VEHICLE INFORMATION

MECHANICAL 6 Cylinder Gas Automatic **AWD Pwr Brakes** 2.5 L

INTERIOR Clean

BLK - Leather Int Odor: OK Regular Dash

OPTIONS

Pwr Lock Pwr Window Tilt Steering Cruise Ctl CD Player Dual Air Bags **ABS Brakes Directional Stability Control**

Memory Seat NO Rear Air Conditioning

Warranty Books HomeLink

Parking Distance Control 7 Passenger Seating **Traction Control** Trip Counter Power Mirrors

Rear Wiper Tinted Windows Headphones

Pwr Steering Pwr Seats - Both

A/C

Rear Defrost Side Air Bags

Telescopic Steering Wheel Owner's Manual

Maintenance Records **Heated Seats**

Dual Air Conditioning Third Seat

Fog Lamps US EPA Label Keyless Entry Luggage Rack Trip Computer Floor Mats Hand Tool Kit

Steering Wheel Audio Control

FLUID LEVELS Fuel Level: Full

TIRES AND WHEELS

LF - 9/32 AURORA 225/55R18 RF - 6/32 AURORA 225/55R18 LR - 7/32 AURORA 225/55R18 RR - 6/32 AURORA 225/55R18

SP - 4/32 Mini Tire Condition: Good Wheels - Alloy

ANNOUNCED CONDITION: AWD; BOOKS; KEY; HEADPHONES

KEYS

Master Key - 2

Remote Key/Fob - 2

INTERNET REMARKS:

REMARKS/ADDITIONAL DAMAGE:

DISCLOSURES:

NOTES TO CONSIGNOR:

REMARKS:

2004 VOLVO XC90 - BLACK

VIN: YV1CZ91H241094954 Work Order #: 2448905
MANHEIM AUTO AUCTION

DAMAGES

				REPAIR	PAINT	PART	TOTAL
	DESCRIPTION	CONDITION	SEV.	HOURS	HOURS	HOURS	HOURS
	LR Door	Ding	1" to 2"	.00	.00	.00	.00
	Spare Tire	Missing	None	.00	.00	.00	.00
	RF Door	Ding	Less 1"	.00	.00	.00	.00
	RR Door	Ding	Less 1"	.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
-00	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	L Qtr Panel	Prev Repair	Acceptable	.00	.00	.00	.00
			TOTALS	.00	.00	.00	.00

Print