



## 2004 VOLVO XC90 - BLUE

VIN: YV1CZ59HX41040346 Work Order #: 2451248  
MANHEIM AUTO AUCTION

**VIN:** YV1CZ59HX41040346  
**Body Style:** Sport Utility Vehicle -  
Pwr Glass Sun Roof  
**Ext Color/Code:** BLUE  
**Int Color/Code:** BLK  
**Mileage:** 56,283  
**Seller:** HANN FINANCIAL  
SERVICES  
**Title State:** NY  
**Certified:** No  
**Condition/Grade:** Grade 4, Clean  
**Sale:** 63  
**Lane:** 20  
**Run:** 527  
**Inspection:** BHILL 10/01/2007  
**Drivable:** Yes



### VEHICLE INFORMATION

#### MECHANICAL

5 Cylinder Gas  
Automatic  
AWD  
Pwr Brakes  
2.5 L

#### FLUID LEVELS

Fuel Level: Empty

#### TIRES AND WHEELS

Left Front: 9/32" GOODYEAR 235/60R18  
Right Front: 9/32" GOODYEAR 235/60R18  
Left Rear: 9/32" GOODYEAR 235/60R18  
Right Rear: 9/32" GOODYEAR 235/60R18  
Spare: 0/32" GOODYEAR 235/60R18

**Tire Condition:** Good

**Wheels:** Alloy

#### INTERIOR

Average  
BLK - Leather  
Int Odor: OK  
Regular Dash

#### KEYS

Combo Key - 2

#### OPTIONS

Pwr Lock  
Pwr Window  
Tilt Steering  
Cruise Ctl  
CD Player  
Dual Air Bags  
ABS Brakes  
4 Door  
Memory Seat  
Heated Seats  
Dual Air Conditioning  
HomeLink  
Security System  
Luggage Rack  
Trip Computer  
Cargo Cover  
Tinted Windows  
Pwr Steering  
Pwr Seats - Both  
A/C  
Rear Defrost  
Side Air Bags  
Telescopic Steering Wheel  
Owner's Manual  
Directional Stability Control  
CD Changer - OEM - 6.00  
NO Rear Air Conditioning  
Third Seat  
Fog Lamps  
Traction Control  
Trip Counter  
Power Mirrors  
Rear Wiper  
Steering Wheel Audio Control

**ANNOUNCED CONDITION:** AWD

**INTERNET REMARKS:**

**REMARKS/ADDITIONAL DAMAGE:**

**DISCLOSURES:**

**NOTES TO CONSIGNOR:**





**REMARKS:**

## 2004 VOLVO XC90 - BLUE

VIN: YV1CZ59HX41040346 Work Order #: 2451248

MANHEIM AUTO AUCTION

### DAMAGES

	DESCRIPTION	CONDITION	SEVERITY	REPAIR HOURS	PAINT HOURS	PART HOURS	TOTAL HOURS
	LF Door	Dings	PDR/3	.00	.00	.00	.00
	LR Door	Dings	PDR/2	.00	.00	.00	.00
	Rear Bumper	Dent	1" to 2"	1.00	3.00	.00	4.00
	RR Door	Dings	PDR/2	.00	.00	.00	.00
	Oil	Sludge		.00	.00	.00	.00
 Overall Image Not Available	Overall Picture	Ovrall Picture		.00	.00	.00	.00
 Overall Image Not Available	Overall Picture	Ovrall Picture		.00	.00	.00	.00
 Overall Image Not Available	Overall Picture	Ovrall Picture		.00	.00	.00	.00
 Overall Image Not Available	Overall Picture	Ovrall Picture		.00	.00	.00	.00
TOTALS				1.00	3.00	.00	4.00

### REPAIRED

DESCRIPTION	CONDITION	SEVERITY	REPAIR HOURS	PAINT HOURS	PART HOURS	TOTAL HOURS
Windshield	Multiple Chips		.00	.00	.00	.00
Oil	Dirty LOF		.00	.00	.00	.00
Warning - Engin	On SERVICE		.00	.00	.00	.00
TOTALS			.00	.00	.00	.00

Print