



2004 BMW X3 3.0L - SILVER G

VIN: WBXPA934X4WC31074 Work Order #: 6621707
NATIONAL AUTO DEALERS EXCHANGE

VIN: WBXPA934X4WC31074
Body Style: 4Dr CUV - Panoramic
Ext Color/Code: SILVER G - A08
Int Color/Code: BLA
Mileage: 48,770
Seller: FINANCIAL SERVICES REMARKETING (LEASE)
Title State: NY
Certified: No
Condition/Grade: Grade 4, Clean
Sale: 49
Lane: 2
Run: 196
Inspection: EFLUKEY 11/09/2007
Drivable: Yes
Factory Category: Ful
In Service Date: 06/30/2004



VEHICLE INFORMATION

MECHANICAL

6 Cylinder Gas
 Steptronic
 AWD
 Pwr Brakes
 3.0 L

INTERIOR

Odometer - 6 Digits Digital
 Operable
 Clean
 BLA - Leather
 Int Odor: OK
 Regular Dash

OPTIONS

Pwr Lock
 Pwr Window
 Tilt Steering
 Cruise Ctl
 CD Player
 Dual Air Bags
 Owner's Manual
 Tinted Windows
 Trip Counter
 Power Trunk/Liftgate
 On-Board Computer
 DSC-Dynamic Stability Control
 Steering Wheel Audio Control
 Panoramic Glass Roof
 Premium Package
 Cargo Cover
 Memory Seat
 Telescopic Steering Wheel
 Panoramic Glass Roof
 Rain Sensor Windshield
 Power Seats - Dual
 Pwr Steering
 Pwr Seats - Both
 A/C
 Rear Defrost
 Side Air Bags
 Power Mirrors
 ABS Brakes
 Fog Lamps
 Rear Wiper
 Luggage Rack
 Floor Mats
 Security System
 HSW - Heated Steering Wheel
 HDC - Hill Descent Control
 Heated Seats
 ST - Steptronic
 Transmission
 Rain Sensor
 Tire Pressure Monitor
 Heated Steering Wheel
 Directional Stability Control
 Heated Seats - Front

FLUID LEVELS

Fuel Level: 1/4

TIRES AND WHEELS

Left Front: 9/32" KUMHO 235/55R17
 Right Front: 9/32" KUMHO 235/55R17
 Left Rear: 9/32" KUMHO 235/55R17
 Right Rear: 9/32" KUMHO 235/55R17
 Spare: 0/32" Mini
Tire Condition: Good
Wheels: Alloy

KEYS

Master Key - 2
 Spare Key - 1

ANNOUNCED CONDITION: *K1,CD,HS,HSW,PREM PKG,ST,
INTERNET REMARKS:

REMARKS/ADDITIONAL DAMAGE:

DISCLOSURES:

NOTES TO CONSIGNOR: *ULTRA DETAIL,PRE SALE INSP







REMARKS: *ULTRA DETAIL,PRE SALE INSP

2004 BMW X3 3.0L - SILVER G

VIN: WBXPA934X4WC31074 Work Order #: 6621707

NATIONAL AUTO DEALERS EXCHANGE

DAMAGES

| | DESCRIPTION | CONDITION | SEVERITY | REPAIR HOURS | PAINT HOURS | PART HOURS | TOTAL HOURS |
|--|-----------------|----------------|-----------------|--------------|-------------|------------|-------------|
|  | Windshield | Multiple Chips | Less 1" | .00 | .00 | .00 | .00 |
|  | Overall Picture | Ovrall Picture | | .00 | .00 | .00 | .00 |
|  | Overall Picture | Ovrall Picture | | .00 | .00 | .00 | .00 |
|  | Overall Picture | Ovrall Picture | | .00 | .00 | .00 | .00 |
|  | Overall Picture | Ovrall Picture | | .00 | .00 | .00 | .00 |
|  | Overall Picture | Ovrall Picture | | .00 | .00 | .00 | .00 |
| | Rear Bumper | Chipped | Vsbl Close Insp | .00 | .00 | .00 | .00 |
| | RR Door | Ding | PDR/1 | .00 | .00 | .00 | .00 |
| | RR Door | Scratch Light | Less 1" | .50 | .00 | .00 | .50 |
| | TOTALS | | | .50 | .00 | .00 | .50 |

REPAIRED

| DESCRIPTION | CONDITION | SEVERITY | REPAIR HOURS | PAINT HOURS | PART HOURS | TOTAL HOURS |
|-------------|----------------|----------------|--------------|-------------|------------|-------------|
| RR Wheel | Scratch Light | | .00 | .00 | .00 | .00 |
| RF Wheel | Mult Scratches | Surface Damage | .00 | .00 | .00 | .00 |
| | TOTALS | | | .00 | .00 | .00 |

Print