



2005 BMW X3 3.0L - ALPINE W

VIN: WBXPA93485WD14830 Work Order #: 6630307
NATIONAL AUTO DEALERS EXCHANGE

VIN: WBXPA93485WD14830
 Body Style: 4CUV - Panoramic
 Ext Color/Code: ALPINE W - 300
 Int Color/Code: BLA
 Mileage: 29,831
 ECM Mileage:
 Seller: FINANCIAL SERVICES
 REMARKETING
 (LEASE)
 Title State: NY
 Certified: No
 Condition/Grade: 3.0, Average
 Sale: 29
 Lane: 14
 Run: 274
 Inspection: RSCHMIDT99
 06/13/2008
 Drivable: Yes
 Factory: Ful
 Category:
 In Service Date: 05/31/2005



VEHICLE INFORMATION

MECHANICAL

6 Cylinder Gas
 Steptronic
 AWD
 Pwr Brakes
 3.0 L

FLUID LEVELS

Fuel Level: 1/4

TIRES AND WHEELS

Tire	Tread Depth	Brand	Size
Left Front:	7/32"	BRIDGESTONE	235/65R17
Left Rear:	7/32"	BRIDGESTONE	235/65R17
Right Front:	7/32"	BRIDGESTONE	235/65R17
Right Rear:	7/32"	BRIDGESTONE	235/65R17
Spare:	0/32"		

Tire Condition: Average
 Wheels: Alloy

INTERIOR

Odometer - 6 Digits Digital
 Operable
 Average
 BLA - Leather
 Int Odor: OK
 Regular Dash

KEYS

Master Key - 2

OPTIONS

Pwr Lock
 Pwr Window
 Tilt Steering
 Cruise Ctl
 CD Player
 Dual Air Bags
 Owner's Manual
 Fog Lamps
 Rear Wiper
 Floor Mats
 Steering Wheel Audio
 Control
 Panoramic Glass Roof
 Premium Package
 ST - Steptronic
 Transmission
 Woodgrain Interior
 Package
 Telescopic Steering
 Wheel
 Panoramic Glass Roof
 Power Seats - Dual

Pwr Steering
 Pwr Seats - Both
 A/C
 Rear Defrost
 Side Air Bags
 Power Mirrors
 ABS Brakes
 Trip Counter
 On-Board Computer
 DSC-Dynamic Stability
 Control
 HSW - Heated
 Steering Wheel
 HDC - Hill Descent
 Control
 Heated Seats
 Memory Seat
 Rain Sensor
 Tire Pressure Monitor
 Directional Stability
 Control
 Heated Seats - Front

ANNOUNCED CONDITION: *K1,CD,HS,PREM PKG,ST,

INTERNET REMARKS:

REMARKS/ADDITIONAL DAMAGE:

DISCLOSURES:

NOTES TO CONSIGNOR:










REMARKS:

2005 BMW X3 3.0L - ALPINE W

VIN: WBXPA93485WD14830 Work Order #: 6630307

NATIONAL AUTO DEALERS EXCHANGE

DAMAGES

	DESCRIPTION	CONDITION	SEVERITY	REPAIR HOURS	PAINT HOURS	PART HOURS	TOTAL HOURS
	Windshield	Star in Glass	Less 1"	.00	.00	.00	.00
	Rear Bumper	Scratch Heavy TEXTURED	Replacement Req	.00	.00	2.00	2.00
	Cargo Cover	Missing	Vsbl Close Insp	.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Front Bumper	Scratch Light	Acceptable	.00	.00	.00	.00
	LF Door	Ding	PDR/1	.00	.00	.00	.00
	RF Wheel	Scratched	Surface Damage	.00	.00	.00	.00
	RF Door	Dings	PDR/2	.00	.00	.00	.00
	RF Mirror Housi	Scratch Light	1" to 2"	.50	.00	.00	.50
	RR Door	Ding	PDR/1	.00	.00	.00	.00
	RR Wheel	Gouged	1" to 2"	.00	.00	.00	.00
			TOTALS	.50	.00	2.00	2.50

Print